

Område: O1.3 - Henån, Orusts kommun

Sektion: K1

Analys: Odränerad

File Name: O1_3K1-odrän.slp
Last Saved Date: 2001-06-06
Last Saved Time: 10:54:26
Analysis Method: Bishop
Direction of Slip Movement: Left to Right
Slip Surface Option: Grid and Radius

