

Område: O1.2 - Henån, Orusts kommun

Sektion: K1

Analys: Odränerad

File Name: O1_2K1-odrän.slp
 Last Saved Date: 2001-06-07
 Last Saved Time: 08:34:59
 Analysis Method: Bishop
 Direction of Slip Movement: Left to Right
 Slip Surface Option: Grid and Radius

