

Område: O1.2 - Henån, Orusts kommun

Sektion: K1

Analys: Dränerad

File Name: O1\_2K1-drän.slp  
 Last Saved Date: 2001-06-07  
 Last Saved Time: 08:53:44  
 Analysis Method: Bishop  
 Direction of Slip Movement: Left to Right  
 Slip Surface Option: Grid and Radius

