

Område: O1.3 - Henån, Orusts kommun

Sektion: K2

Analys: Odränerad

File Name: O1\_3K2-odrän.slp  
Last Saved Date: 2001-06-06  
Last Saved Time: 17:11:19  
Analysis Method: Bishop  
Direction of Slip Movement: Right to Left  
Slip Surface Option: Grid and Radius

